

FIG. 1
(PRIOR ART)




FIG. 2




FIG. 3




FIG. 4




FIG. 6





FIG. 5




FIG. 7




FIG. 10A




FIG. 10B





FIG. 10C






FIG. 8
(PRIOR ART)




FIG. 8A
(PRIOR ART)




FIG. 9

FIG.11




FIG.12




FIG.13





FIG.13A






FIG.14

Le ≈ 8mm

TIPS	
Ln ≈ 8mm	40
≈ 9mm	30
≈ 10mm	25

Lf ≈ 14mm